

Inspection Photos

API: 05-043-40087

Well Name: [HW-2220S69W \(OWP\) #1](#)

Inspection Date: 12/4/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40087 | Date: 12/4/2019

Inspection Photos



Photo 1. Facing northeast toward the location. There is a small pile of bricks that remain.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40087 | Date: 12/4/2019

Inspection Photos



Photo 2. Facing northeast at the location. Approximately 40'x30' area which has not revegetated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40087 | Date: 12/4/2019

Inspection Photos



Photo 3. Facing northeast toward the surrounding undisturbed pasture.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40087 | Date: 12/4/2019