



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Oct 30, 2019 10:21:03 AM MDT
Server Receive Date:	Oct 30, 2019 10:23:04 AM MDT
Reference Number:	20191030-18121681227
Location:	557 Airpark Dr, Durango, CO 81303, USA Oct 30, 2019 10:20:31 AM MDT [View Map]

Information

Name	colen@horizonenvservices.com
Date	Oct 29, 2019
Well Name	JOHNSON, MW GAS UNIT A 2
API Number	50670656600
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Other
Photo of first corrective action completed	



Completed work description Corrective Action 1

sign

Photo of second corrective action completed



Completed work description of corrective action 2

treated noxious weeds in reclamation area

Photo of third corrective action completed



Completed work description of corrective action 3
Photo of fourth corrective action completed

treated noxious weeds in reclamation area



Completed work description
Completed work description of corrective action 4
Additional photos

treated noxious weeds in reclamation area
treated noxious weeds in reclamation area



Additional photos



Completed work description
Summary of all work completed

treated noxious weeds in reclamation area
treated noxious weeds in reclamation area