



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Nov 5, 2019 4:29:07 PM MST
Server Receive Date:	Nov 5, 2019 4:31:13 PM MST
Reference Number:	20191105-18122168033
Location:	557 Airpark Dr, Durango, CO 81303, USA Nov 5, 2019 4:28:43 PM MST [ <a href="#">View Map</a> ]

## Information

Name	colen@horizonenvservices.com
Date	Nov 5, 2019
Well Name	ANNALA, ROY GAS UNIT A 2
API Number	50670833400
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Land Owner Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

sign

Photo of second corrective action completed



Completed work description of corrective action 2

landowner debris before

Photo of third corrective action completed



Completed work description of corrective action 3  
 Photo of fourth corrective action completed



Completed work description

Completed work description of corrective action 4  
 Additional photos



Additional photos

landowner debris after

weeds treated earlier in season as part of spray  
 program  
 cleaned up landowner debris



Additional photos



Completed work description  
Summary of all work completed

cleaned up landowner debris  
debris cleanup and photos of treated weeds