



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Nov 15, 2019 5:23:16 PM MST
Server Receive Date:	Nov 15, 2019 5:25:22 PM MST
Reference Number:	20191116-18123075377
Location:	557 Airpark Dr, Durango, CO 81303, USA Nov 15, 2019 5:22:44 PM MST [ <a href="#">View Map</a> ]

## Information

Name	colen@horizonenvservices.com
Date	Nov 13, 2019
Well Name	JACQUEZ, THOMAS GAS UNIT A 2
API Number	50670849600
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

sign

Photo of second corrective action completed



Completed work description of corrective action 2

treated musk thistle rosettes

Photo of third corrective action completed



Completed work description of corrective action 3  
 Photo of fourth corrective action completed

treated musk thistle rosettes



Completed work description  
 Completed work description of corrective action 4

mowed weed debris on edge of pad  
 treated musk thistle rosettes and mowed weed debris on edge of pad

Additional photos



Summary of all work completed

treated noxious weeds and mowed weed debris