



Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Dec 9, 2019 9:00:53 AM MST
Server Receive Date:	Dec 9, 2019 9:03:10 AM MST
Reference Number:	20191209-18125639126
Location:	557 Airpark Dr, Durango, CO 81303, USA Dec 9, 2019 9:02:18 AM MST [ <a href="#">View Map</a> ]

Information

Name	colen@horizonenvservices.com
Date	Dec 6, 2019
Well Name	PAN AMERICAN FEE GAS UNIT B 1
API Number	50670579600
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

sign

Photo of second corrective action completed



Completed work description of corrective action 2

before mowing

Photo of third corrective action completed



Completed work description of corrective action 3  
Photo of fourth corrective action completed

after mowing



Completed work description  
Completed work description of corrective action 4  
Summary of all work completed

vegetation removed around equipment  
removed weed debris around equipment and in the  
reclamation area  
removed weed debris from around the equipment  
and the reclamation area