

Ant Hill Unit 20-31  
API: 05-103-09924  
Inspection: 679706499



**Photo 1. Location.**



Ant Hill Unit 20-31  
API: 05-103-09924  
Inspection: 679706499



Photo 2. Location.



Ant Hill Unit 20-31  
API: 05-103-09924  
Inspection: 679706499



**Photo 3. Separators.**



Ant Hill Unit 20-31  
API: 05-103-09924  
Inspection: 679706499



**Photo 4. Tank battery.**