

Location Name: – Gulley 1- D Tank Battery – Treater Spill
Inspection Date: 12/11/2019



Photo # 1 –

Location Name: – Gulley 1- D Tank Battery – Treater Spill
Inspection Date: 12/11/2019



Photo # 2 – Minor oil staining at crude tank loadout area

Location Name: – Gulley 1- D Tank Battery – Treater Spill
Inspection Date: 12/11/2019



Photo # 3 – Animal burrows in tank battery berm



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Gulley 1- D Tank Battery – Treater Spill
Inspection Date: 12/11/2019



Photo # 4 – Animal burrows in tank battery berm



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Gulley 1- D Tank Battery – Treater Spill
Inspection Date: 12/11/2019



Photo # 5 – Oil spill within treater berm



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Gulley 1- D Tank Battery – Treater Spill
Inspection Date: 12/11/2019



Photo # 6 – Oil spill within treater berm



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Gulley 1- D Tank Battery – Treater Spill
Inspection Date: 12/11/2019



Photo # 7 – Oil spill within treater berm



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Gulley 1- D Tank Battery – Treater Spill
Inspection Date: 12/11/2019



Photo # 8 – Animal burrow in treater berm



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Gulley 1- D Tank Battery – Treater Spill
Inspection Date: 12/11/2019



Photo # 9 – Access road northwest toward wellhead



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Gulley 1- D Tank Battery – Treater Spill
Inspection Date: 12/11/2019



Photo # 10 – View north from north side of treater across former pit area (104590).