

Inspection Photos
Location Name: Bernhardt 7-16 Tank Battery
Location ID: 448358



Colorado Oil And Gas Conservation Commission
40.31969, -104.82369, 1391.0m
12/12/2019 12:01:32 PM

Tank battery



Colorado Oil And Gas Conservation Commission
40.31967, -104.82347, 1412.0m
12/12/2019 12:01:41 PM

Crude oil tank berm

Inspection Photos
Location Name: Bernhardt 7-16 Tank Battery
Location ID: 448358



Load valve and stained soil



Load valve and stained soil

Inspection Photos
Location Name: Bernhardt 7-16 Tank Battery
Location ID: 448358



Front of crude oil tanks



Front of crude oil tanks

Inspection Photos
Location Name: Bernhardt 7-16 Tank Battery
Location ID: 448358



Crude oil tank berm



Trash

Inspection Photos
Location Name: Bernhardt 7-16 Tank Battery
Location ID: 448358



Trash



Unused equipment

Inspection Photos
Location Name: Bernhardt 7-16 Tank Battery
Location ID: 448358



Unused equipment