

Inspection Photos
Location Name: Shaw 15-20
Location ID: 331000



Photo 1 WH sign

Photo 2 dead weeds around location fence

Inspection Photos
Location Name: Shaw 15-20
Location ID: 331000



Photo 3 Stained soil by gas engine exhaust

Photo 4 Stained soil under engine skid

Inspection Photos
Location Name: Shaw 15-20
Location ID: 331000



Colorado Oil & Gas Conservation Commission
40.12029, -105.02379, 4844.1ft, 95°
12/12/2019 09:32:48

Photo 5 Stained soil by gas engine skid