

Inspection Photos

API: 05-071-08367

Operator: TIMBER CREEK OPERATING

Inspection Date: 12/12/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08367 | Date: 12/12/2019

Inspection Photos



Photo 1. Facing west toward the location. Well sign is posted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08367 | Date: 12/12/2019

Inspection Photos



Photo 2. Facing toward the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08367 | Date: 12/12/2019

Inspection Photos



Photo 3. The electric fence around the pit is in disrepair.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08367 | Date: 12/12/2019