

# *Inspection Photos*

*Loc#335405*

*Operator: Caerus*

*Inspection Number: 692401686*

*Inspection Date: 12/10/19*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to South. Insert is unmarked Anchor.

December 10, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus GMU Loc#335405



Photo#2:  
View along Cut Slope. Insert is SW Reclamation area.



Photo#3:  
Close up of concern on Cut Slope.

December 10, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus GMU Loc#335405



Photo#4:  
Views along access road.



Photo#5:  
Views along access road.

December 10, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus GMU Loc#335405