

**Inspection Photos**  
**Location Name: Firestone A, B, C, D #1 Wells**  
**Location ID:**



**Photo1 Weeds on location appear to have been cut**



**Photo 2 Firestone A #1 weeds appear to have been cut & removed**

**Inspection Photos**  
**Location Name: Firestone A, B, C, D #1 Wells**  
**Location ID:**



**Photo 3 Firestone B #1 Weeds around PU appear to have been cut.**



**Photo 4 weeds around electric panel for all 4 wells appear to have been cut.**



**Inspection Photos**  
**Location Name: Firestone A, B, C, D #1 Wells**  
**Location ID:**



**Photo 5 Firestone C #1 Weeds around PU appear to have been cut. Unused equip. (ladder) remains on ground**



**Photo 6 Firestone D #1 Weeds around PU appear to have been cut.**

**Inspection Photos**  
**Location Name: Firestone A, B, C, D #1 Wells**  
**Location ID: 318517**



**Photo 7 Firestone D #1 Unused riser appears to have been bull plugged but not LOTO**



**Photo 8 Firestone D #1 unused equip. 1" electrical conduit appears to have been removed**