

## Inspection Photos

Location Name: CAERUS PICEANCE LLC RADEL-68S96W /11NWSW,

Location ID: 334347



Network time is not synchronize  
Local:Dec 16, 2019 at 12:25:53 PM MS  
+39.3625,-108.073



Network time is not synchronize  
Local:Dec 16, 2019 at 12:30:37 PM MS  
+39.3615,-108.085

Photo #0258 photo from SW corner of location.

Photo #0262 unused pipe stand.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC RADEL-68S96W /11NWSW,

Location ID: 334347



Photo #0260 Multiple holes in tank containment liner.



Photo #0261 Multiple holes in tank containment liner.