

Inspection Photos

Loc#336021

Operator: Ursa

Inspection Number: 692401692

Inspection Date: 12/10/19






Photo#1:
Overview of Location to Northwest.

December 10, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Snyder Loc#336021



Photo#2:
Wildlife Escape Board in cellar of Well #045-10901 is improperly adjusted.

December 10, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Snyder Loc#336021



Photo#3:
View of North Reclamation area.

December 10, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Snyder Loc#336021



Photo#4:
View of West Reclamation area.

December 10, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Snyder Loc#336021