

**Inspection Photos**  
**Location Name: Booth Pad**  
**Location ID: 430168**



Colorado Oil and Gas Conservation Commission  
40.55146, -104.62902, 1465.9m, 36°  
Dec 18, 2019 12:10:35

**Photo 1: Riser removed**



Colorado Oil and Gas Conservation Commission  
40.55172, -104.62876, 1463.5m, 61°  
Dec 18, 2019 12:25:09

**Photo 2: Wellhead Sign**



**Inspection Photos**  
**Location Name: Booth Pad**  
**Location ID: 430168**



**Photo 3: Wellhead**



**Photo 4: Stained soil removed**

Inspection Photos  
Location Name: Booth Pad  
Location ID: 430168



Photo 5: Wellhead Sign




Photo 6: Wellhead

Inspection Photos  
Location Name: Booth Pad  
Location ID: 430168



Colorado Oil and Gas Conservation Commission  
40.55224, -104.6288, 1471.8m, 42°  
Dec 18, 2019 12:31:26



Colorado Oil and Gas Conservation Commission  
40.55226, -104.62884, 1472.0m, 15°  
Dec 18, 2019 12:31:36

Photo 7: Appears stained soil removed (snow covering area)

Photo 8: Wellhead Sign

Inspection Photos  
Location Name: Booth Pad  
Location ID: 430168



Photo 9: Wellhead



Photo 10: Stained soil

Inspection Photos  
Location Name: Booth Pad  
Location ID: 430168



Colorado Oil and Gas Conservation Commission  
40.55276, -104.62891, 1473.6m, 193°  
Dec 18, 2019 12:38:17

Photo 11: Tank Battery Sign



Colorado Oil and Gas Conservation Commission  
40.55283, -104.62864, 1473.2m, 219°  
Dec 18, 2019 12:38:50

Photo 12: Tank Battery

Inspection Photos  
Location Name: Booth Pad  
Location ID: 430168



Photo 13: H2O tank with labeling



Photo 14: H2O tank with labeling

Inspection Photos  
Location Name: Booth Pad  
Location ID: 430168



Photo 15: H2O tank with labeling



Photo 16: Gas meter housing removed