

On November 20, 2019, COGCC Environmental Staff (John Heil and Steven Arauza) conducted an environmental field inspection of XTO ENERGY INC (XTO operator #100264) Location ID 316678 Yellow Creek Federal XOM 2-35-1, Spill/Release ID 468770. Weather was rainy and temperatures about 45 degrees Fahrenheit. See summary for details:

- Additional excavation on the north, east, and west side of the tank battery.
- Additional excavation on the south side of the pump house.
- Gravel removed from the base of the tank battery except for underneath of the Steel ASTs.
- Trash and debris within the tank battery secondary containment.
- 1-inch holes in the secondary containment liner located at the northeast corner of the tank battery. Fluids can be seen daylighting on the exterior of the tank battery adjacent to the location of the observed hole.
- Multiple patches missing on the northeast corner of the tank battery.
- Bermed, stockpiled soil and gravel on the east side of the well pad.