

Inspection Photos

Location Name: Yellow Creek Federal XON 2-35-1
Location ID: Location ID: 316678 & Spill/Release ID: 468770
Inspection Date: November 20, 2019



Photo #1 – Aerial view of the location.



Photo #2 – View of the additional excavation on the west side of the tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Yellow Creek Federal XON 2-35-1

Location ID: Location ID: 316678 & Spill/Release ID: 468770

Inspection Date: November 20, 2019



Photo #9 – View of the XTO tank sign adjacent to the BOBCO LP sign.



Photo #10 – View of the BOBCO LP tank sign on the southwest produced water tank.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Yellow Creek Federal XON 2-35-1

Location ID: Location ID: 316678 & Spill/Release ID: 468770

Inspection Date: November 20, 2019



Photo #3 - View of the additional excavation on the north side of the tank battery.



Photo #4 - View of the additional excavation on the east side of the tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Yellow Creek Federal XON 2-35-1

Location ID: Location ID: 316678 & Spill/Release ID: 468770

Inspection Date: November 20, 2019



Photo #5 - View of the additional excavation on the south side of the pump house.



Photo #6 – View of the trash within the secondary containment and the removed gravel.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Yellow Creek Federal XON 2-35-1

Location ID: Location ID: 316678 & Spill/Release ID: 468770

Inspection Date: November 20, 2019



Photo #7 - View removed gravel in the tank battery.



Photo #8 – View of the 1-inch hole on the northeast corner of the tank battery (Red circle).



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Yellow Creek Federal XON 2-35-1

Location ID: Location ID: 316678 & Spill/Release ID: 468770

Inspection Date: November 20, 2019



Photo #9 - View of the 1-inch hole on the northeast corner of the tank battery (Red circle).



Photo #10 – View of fluids daylighting outside of the secondary containment adjacent to the observed 1-inch hole in the liner.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Yellow Creek Federal XON 2-35-1

Location ID: Location ID: 316678 & Spill/Release ID: 468770

Inspection Date: November 20, 2019



Photo #13 – View of the patches missing on the northeast corner of the tank battery secondary containment (Red circle).



Photo #14 – View of the stockpiled soil and gravel on the east side of the well pad.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources