

Inspection Photos
Location Name: Guthrie #1
Location ID: 320185



Colorado Oil and Gas Conservation Commission
39.99547, -104.86267, 1525.6m
Dec 18, 2019 09:17:08

Photo 1 WH sign



Colorado Oil and Gas Conservation Commission
39.99489, -104.86278, 1519.6m
Dec 18, 2019 09:11:18

Photo 2 access road deep ruts. No BMP's in place road not properly maintained.

Inspection Photos
Location Name: Guthrie #1
Location ID: 320185



Photo 3 Weed on location and Debris



Photo 4 Debris: dead weeds and branches on location.

Inspection Photos
Location Name: Guthrie #1
Location ID: 320185



Photo 5 Weeds around electric panel



Photo 6 Weeds and Guy line anchor not properly marked

Inspection Photos
Location Name: Guthrie #1
Location ID: 320185



Photo 7 Pile of debris and dirt next to well head. Weeds on location.



Photo 8 Unused equipment: What appears to be old well head and flowlines

Inspection Photos
Location Name: Guthrie #1
Location ID: 320185



Photo 9 Unused equipment: What appears to be old well head and flowlines



Photo 10 Stained soil and grease around well head