

Inspection Photos
Location Name: Schaefer LD 13-032HC
Location ID:440718



Photo 1 loc pic



Photo 2 rock tracking pad impacted with sediment.

Inspection Photos
Location Name: Schaefer LD 13-032HC
Location ID:440718



Photo 3 Sediment being carried off right away on to county road



Photo 4 Sediment being carried off right away on to county road