

Final Reclamation Inspection

December 17, 2019

Operator: HIGHPOINT OPERATING CORPORATION- 10071

Location ID: 318581

Inspection Document #: 697500924

Weld County, CO

SESE Section 36 T2N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: STATE #36-3
Location ID: 318581



Photo 1. Photo taken from the eastern access road, facing East. Photo illustrates gravel remaining along the access road likely due to equipment remaining at location. Note: Reference crop areas appear to be planted in winter wheat.

Inspection Photos
Location Name: STATE #36-3
Location ID: 318581



Photo 2. Photo taken from the eastern access road, facing West. Photo illustrates access road has not been contoured to match the surrounding landscape.

Inspection Photos
Location Name: STATE #36-3
Location ID: 318581



Photo 3. Close up photo taken along the portion of the access road that was illustrated in Photo 1.



Photo 4. Close up photo taken from a reference crop area adjacent to the access road.

Inspection Photos
Location Name: STATE #36-3
Location ID: 318581



Photo 5. Photo taken from the location, facing West. Operator has failed to remove all equipment since plugging operations.