

Final Reclamation Inspection

December 17, 2019

Operator: HIGHPOINT OPERATING CORPORATION- 10071

Location ID: 318568

Inspection Document #: 697500926

Weld County, CO

NWSW Section 31 T2N R62W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HAROLD #1
Location ID: 318568



Photo 1. Photo taken from the western access road, facing East. Photo illustrates gravel remaining along the access road likely due to equipment remaining at location.

Inspection Photos
Location Name: HAROLD #1
Location ID: 318568



Photo 2. Close up photo taken along the portion of the access road that was illustrated in Photo 1.



Photo 3. Close up photo taken from a reference crop area adjacent to the access road.

Inspection Photos
Location Name: HAROLD #1
Location ID: 318568



Photo 4. Photo taken from the location, facing Northeast. Operator has failed to remove all equipment since plugging operations.



Photo 5. Photo taken of the equipment illustrating it is not in use.