

Inspection Photos Location #324439



Location



Location

Inspection Photos Location #324439



Debris



Debris

Inspection Photos Location #324439



Debris



Debris

Inspection Photos Location #324439



COGCC
39.50914, -107.52377, 1911.0m, 5°
12/18/2019 01:12:16 PM

Debris



COGCC
39.5091, -107.52375, 1910.0m, 93°
12/18/2019 01:12:32 PM

Debris

Inspection Photos Location #324439



Debris
Pipe disconnected



Debris
Pipe disconnected

Inspection Photos Location #324439



Debris

Inspection Photos Location #324439



Missing tank information on fuel barrel. Photo from previous inspection.



Missing tank information on fuel barrel. No capacity, or operator.

