

Inspection Photos  
Location Name: Frank Stermole #1 TB  
Location ID: 445507



Photo 1 TB sign

Photo 2 TB

**Inspection Photos**  
**Location Name: Frank Stermole #1 TB**  
**Location ID: 445507**



**Photo 3 Gas Meter Run**

**Photo 4 Heated Horizontal Separator**

**Inspection Photos**  
**Location Name: Frank Stermole #1 TB**  
**Location ID: 445507**



**Photo 5 ECD**

**Photo 6 Dead weeds inside Tank berm**

**Inspection Photos**  
**Location Name: Frank Stermole #1 TB**  
**Location ID: 445507**



**Photo 7 Produced water Berm inadequate**