

## Inspection Photos

Location Name: CAERUS PICEANCE LLC LINDAUER-68S96W /3SWSE

Location ID: 334105



Photo #0276 photo from entrance to location.



Photo #0278 Trash and weeds inside tank containment.



## Inspection Photos

Location Name: CAERUS PICEANCE LLC LINDAUER-68S96W /3SWSE

Location ID: 334105



**Photo #0279 Multiple holes in tank containment liner.**



**Photo #0280 Multiple holes in tank containment liner.**