

Inspection Photo

Loc#452807

Operator: Laramie

Inspection Number: 692401699

Inspection Date: 12/11/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from Access Road.

December 11, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Cascade Creek Loc#452807



Photo#2:
Silt fence in disrepair along site perimeter.



Photo#3:
Silt fence in disrepair along site perimeter.

December 11, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Cascade Creek Loc#452807