

Inspection Photos
Location Name: DOW-65N63W /28SWNE
Location #: 331413



Colorado Oil & Gas Conservation Commission
40.37523, -104.43843, 1369.0m, 145°
11/19/2019 04:35:28 PM

Photo #1
DOW 32-28 Battery site
Abandoned | Most equipment removed
Reclamation progressing
Unused Gas meter runs
prior insp.



Colorado Oil & Gas Conservation Commission
40.37521, -104.4385, 1367.0m, 131°
12/18/2019 11:47:15 AM

Photo #2
DOW 32-28 Battery site
Abandoned | Most equipment removed
Reclamation progressing
Marked & capped risers: 3

Inspection Photos
Location Name: DOW-65N63W /28SWNE
Location #: 331413



Photo #3
DOW 32-28 Wellsite
Plugged & Abandoned | PA
Unused equipment
Deadman anchors – 4 on site
prior insp.



Photo #4
DOW 32-28 Wellsite
Unused equipment
Deadman anchors – 4 on site: REMOVED

Inspection Photos
Location Name: DOW-65N63W /28SWNE
Location #: 331413



Photo #5
DOW 32-28 Wellsite
Plugged & Abandoned | PA
Junk
Cut casing pipe, well fence
prior insp.



Photo #6
DOW 32-28 Wellsite
Plugged & Abandoned | PA
Junk
Cut casing pipe, well fence: REMOVED

Inspection Photos
Location Name: DOW-65N63W /28SWNE
Location #: 331413



Photo #7
DOW 32-28 (05-123-20656) Wellsite
Plugged & Abandoned | PA
~ 20 yds.
Appears to be cut & capped
Reclamation progressing
prior insp.