

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402208899
Receive Date:
12/18/2019

Report taken by:
John Heil

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27.

This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATON

Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u>	Operator No: <u>96850</u>	Phone Numbers
Address: <u>PO BOX 370</u>		
City: <u>PARACHUTE</u>	State: <u>CO</u>	Zip: <u>81635</u>
Contact Person: <u>Michael Gardner</u>	Email: <u>MGardner@terraep.com</u>	Phone: <u>(970) 263-2760</u>
		Mobile: <u>(970) 623-4875</u>

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 11556 Initial Form 27 Document #: 401705739

PURPOSE INFORMATION

- | | |
|--|--|
| <input type="checkbox"/> 901.e. Sensitive Area Determination | <input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water |
| <input checked="" type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure | <input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b. |
| <input type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation | <input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project |
| <input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste | <input type="checkbox"/> Rule 906.c.: Director request |
| <input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure | <input type="checkbox"/> Other _____ |

SITE INFORMATION

N Multiple Facilites (in accordance with Rule 909.c.)

Facility Type: <u>PIT</u>	Facility ID: <u>277092</u>	API #: _____	County Name: <u>GARFIELD</u>
Facility Name: <u>CHEVRON TR 14-36-597</u>	Latitude: <u>39.564516</u>	Longitude: <u>-108.233731</u>	
	** correct Lat/Long if needed: Latitude: <u>39.564967</u>	Longitude: <u>-108.232718</u>	
QtrQtr: <u>SWSW</u>	Sec: <u>36</u>	Twp: <u>5S</u>	Range: <u>97W</u>
	Meridian: <u>6</u>	Sensitive Area? <u>Yes</u>	

SITE CONDITIONS

General soil type - USCS Classifications OH Most Sensitive Adjacent Land Use Rangeland

Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

Willow Creek, an ephemeral drainage lies approxmiately 600ft to the west

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- | | | |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste | <input checked="" type="checkbox"/> Other E&P Waste | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids | _____ |
| <input type="checkbox"/> Oil | <input type="checkbox"/> Tank Bottoms | |
| <input type="checkbox"/> Condensate | <input type="checkbox"/> Pigging Waste | |
| <input type="checkbox"/> Drilling Fluids | <input type="checkbox"/> Rig Wash | |
| <input type="checkbox"/> Drill Cuttings | <input type="checkbox"/> Spent Filters | |
| | <input checked="" type="checkbox"/> Pit Bottoms | |
| | <input type="checkbox"/> Other (as described by EPA) | _____ |

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
No	SOILS	None	Confirmation sampling, visual assessment

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

At the location(s) of the pit which are the furthest downgradient, lowest in elevation and/or have the potential for pooling of liquid, field-screening will be performed and will utilize appropriate field equipment which may include, but is not limited to the following.
-PetroFlag unit,
-photoionization gas detector (PID),

Confirmation sample(s), Rule 905.b.(4), will be collected and submitted for lab analysis and verification to confirm compliance with Rule 910 and Table 910-1, relative to the aforementioned field screen activity.

Other areas of the pit walls and floor will be inspected for evidence of impact via field screening and visual observation. Grab samples will be collected, as appropriate, to demonstrate diligence and thoroughness of investigation activities performed as directed in Rule 905.b.(1). In addition, all field screening activities and results will be documented and compiled into a summary report, table and/or map to be provided with the Notice of Completion (NOC) Report.

Grab sample(s) will be submitted for laboratory analysis to confirm field screening activities. Sub-liner sample analytes will include considerations identified by Rule 910 and all contaminants of concern for soils from Table 910-1.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Five (5) grab samples will initially be collected from the pit subsoils along the side wall and bottom. Sample locations will be provided in a sample location map attached to the closure summary.

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 5
Number of soil samples exceeding 910-1 0
Was the areal and vertical extent of soil contamination delineated? _____
Approximate areal extent (square feet) 0

NA / ND

-- Highest concentration of TPH (mg/kg) 36
-- Highest concentration of SAR 5.4
BTEX > 910-1 No
Vertical Extent > 910-1 (in feet) 0

Groundwater

Number of groundwater samples collected 0
Was extent of groundwater contaminated delineated? No
Depth to groundwater (below ground surface, in feet) 100'
Number of groundwater monitoring wells installed 0
Number of groundwater samples exceeding 910-1 0

____ Highest concentration of Benzene (µg/l) _____
____ Highest concentration of Toluene (µg/l) _____
____ Highest concentration of Ethylbenzene (µg/l) _____
____ Highest concentration of Xylene (µg/l) _____
____ Highest concentration of Methane (mg/l) _____

Surface Water

0 Number of surface water samples collected
0 Number of surface water samples exceeding 910-1
If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Three (3) background samples were collected from an upgradient undisturbed location

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) _____ Volume of liquid waste (barrels) _____

Is further site investigation required?

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? Yes _____

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

The pit fluids and any sludge/solids on the pit bottom (above the liner) were hydro-vac'd out and hauled to the TEP Centralized Waste Water facility for disposal. The pit poly liner and underlying supporting layers were cut in sections and hauled to West Garfield County Landfill and disposed of as solid waste. No underlying soil impacts containing hydrocarbons were observed in either the field screening or confirmation data sampling and therefore no excavation of soils was conducted at this time.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Field screening results varied between 5-31 ppm with the Photoionizing Detection (PID) unit and 16-62 mg/kg with the Petroflag. Confirmation soil samples were collected at the mid-point on the pit side walls (~8 bgs) as well as off the bottom of the pit at the lowest point (~12ft bgs). Analytical results indicate that the underlying soils on the side wall and pit bottom do not exceed COGCC Table 910-1 thresholds for hydrocarbons. The only exceedances to Table 910-1 noted were for arsenic.

Soil Remediation Summary

In Situ

- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Air sparge / Soil vapor extraction
- _____ Natural Attenuation
- _____ Other _____

Ex Situ

- _____ Excavate and offsite disposal
- _____ If Yes: Estimated Volume (Cubic Yards) _____
- _____ Name of Licensed Disposal Facility or COGCC Facility ID # _____
- _____ Excavate and onsite remediation
- _____ Land Treatment
- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Other _____

Groundwater Remediation Summary

- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Air sparge / Soil vapor extraction
- _____ Natural Attenuation
- _____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

REMEDATION PROGRESS UPDATE

PERIODIC REPORTING

Frequency: Quarterly Semi-Annually Annually Other Final Closure _____

Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report

Other Notice of Completion (NOC) _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No _____

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

REMEDATION COMPLETION REPORT

REMEDATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? Yes _____

Do all soils meet Table 910-1 standards? Yes _____

Does the previous reply indicate consideration of background concentrations? Yes _____

Are the only residual soil impacts pH, SAR, or EC at depths greater than 3 feet below ground surface? _____

Does Groundwater meet Table 910-1 standards? Yes _____

Is additional groundwater monitoring to be conducted? No _____

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The pit will be reclaimed to the present grade of the location or to the approximate original contour of the landscape and consistent with the 1000-series Rule. Seeding of the disturbed area will be performed in accordance with its' intended use. The seed mix will be prescribed by the landowner. There are no known noxious weeds in the immediate area of the disturbance.

Is the described reclamation complete? Yes _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim? Final?

Did the Surface Owner approve the seed mix? Yes _____

If NO, does the seed mix comply with local soil conservation district recommendations? Yes _____

IMPLEMENTATION SCHEDULE

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, if known. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 05/14/2019

Date of commencement of Site Investigation. 05/15/2019

Date of completion of Site Investigation. 05/20/2019

REMEDIAL ACTION DATES

Date of commencement of Remediation. _____

Date of completion of Remediation. _____

SITE RECLAMATION DATES

Date of commencement of Reclamation. _____

Date of completion of Reclamation. _____

OPERATOR COMMENT

Please forward to John Heil.

RE: TR 14-36-597 Production Pit – Closure Request.

Information in this Supplemental Form 27 includes initial site investigation actions, pit liner disposal, field screening, confirmation soil sampling and mapping. Both field screening results and confirmation analytical data indicate that the pit subliner soils do not contain hydrocarbon impacts exceeding COGCC Table 910-1 thresholds.
The only exceedances observed were for arsenic and are consistent with background concentrations for the Trail Ridge area. TEP is requesting relief to arsenic exceedance as outlined in COGCC FAQ 31.

TEP is requesting closure of the TR 14-36-597 production pit (Facility ID 277092 , REM# 11556).

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Michael Gardner _____

Title: TEP Environmental _____

Submit Date: 12/18/2019 _____

Email: MGardner@terraep.com _____

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: John Heil _____

Date: 12/19/2019 _____

Remediation Project Number: 11556 _____

COA Type**Description**

COA Type	Description

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

Att Doc Num	Name
402208899	FORM 27-SUPPLEMENTAL-SUBMITTED
402208921	SOIL SAMPLE LOCATION MAP
402208923	ANALYTICAL RESULTS
402208924	ANALYTICAL RESULTS
402208926	ANALYTICAL RESULTS

Total Attach: 5 Files

General Comments**User Group****Comment****Comment Date**

User Group	Comment	Comment Date
Environmental	After review of the data presented, elevated levels of [SAR/EC/pH] exist deeper than three feet below ground surface. Per guidance in FAQ 32, elevated levels of [SAR/EC/pH] at three feet below ground surface or deeper should not adversely affect the successful reclamation of the site. If groundwater is found to be impacted, or if reclamation is not compliant with the 1000-series rules, additional remediation activities may be required at the site. It appears that no further action is necessary at this time and COGCC approves the closure request.	12/18/2019

Total: 1 comment(s)