

Inspection Photos


Loc#335339

Operator: Grizzly

Inspection Number: 692401732

Inspection Date: 12/12/19





Photo#1:
Overview of location to North.

December 12, 2019



Photo#2:
View of Cut slope re-vegetation.



Photo#3:
Rocked BMPs.

December 12, 2019



Photo#4:

Well #045-10445: Cellar allows ingress to cellar by wildlife with no means of egress.

December 12, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Grizzly GGU Loc#335339