

WELL SITE INSPECTION FORM

WELL NAME Mallon 18-6
 OPERATOR Mallon
 LOCATION 18, 71, 87u
 FIELD WC

API NUMBER 05 - 107 - 6152
 PERMIT NUMBER _____
 COUNTY Routt
 INSPECTOR Katy Buell

AL/PA/DA INSPECTION RESULTS:

WELL STATUS:

PASS(Y) Y FAIL(N) _____ DATE 10-4-89 FN _____ FD _____ WO _____

DATE OF INSPECTION BEFORE/DURING DRILLING _____

CASING SIZE _____ DEPTH SET _____ CMT VOL _____ WOC _____
 CONSISTENT WITH APD CASING PROGRAM? _____ RETURNS _____
 RIG _____ BOP'S _____ CONTACT _____

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION _____

PIPE SET? _____ COMPLETION RIG/ACTIVITY _____
 DRILLING PITS: CLOSED _____ OPEN _____ WELLHEAD SYSTEM INSTALLED _____
 TANK ID: YES _____ NO _____ NA _____ WELL SIGN: YES _____ NO _____
 SKIM PIT: _____ gal TANKS: () _____ bbls
 EQUIPMENT _____

BRADENHEAD PRESSURE _____ FLUID: NO _____ YES _____ TYPE _____
 METER RUN: YES _____ NO _____ WELL STATUS: PR _____ TA _____ SI _____ WELL CAT 3- _____

AL/PA/DA INSPECTION

DATE PLUGGED: _____ DATE PERMIT EXPIRED: _____
 HOLE PLUGGED: YES ☒ NO _____ PITS BACKFILLED: YES _____ NO _____
 MATERIAL BURIED: YES _____ NO _____ NA _____ SITE CLEAN: YES _____ NO _____
 BOND RELEASE OK: YES _____ NO _____ FED _____ HOLE MARKER: YES _____ NO _____

DATE OF SAFETY/STATUS INSPECTION _____

COMMENTS Rates locked. Restoration satisfactory according to Wolf Mtn Ranch people (landowners.)



00221449