

Inspection Photos
Location Name: Blehm 19-L Pad
Location ID: 433645



Photo 1: Wellhead Sign



Photo 2: Wellhead



Inspection Photos
Location Name: Blehm 19-L Pad
Location ID: 433645




Photo 3: Stained soil



Photo 4: Wellhead Sign

Inspection Photos
Location Name: Blehm 19-L Pad
Location ID: 433645



Photo 5: Wellhead



Photo 6: Tank Battery Sign

Inspection Photos
Location Name: Blehm 19-L Pad
Location ID: 433645



Photo 7: Tank Battery