

Inspection Photos
Location Name: Pierce Unit-Kennedy #3
Location ID: 323392



Photo 1: Pumpjack Sign



Photo 2: Pumpjack

Inspection Photos
Location Name: Pierce Unit-Kennedy #3
Location ID: 323392



Photo 3: Unknown contents in container



Photo 4: Container next to pumpjack

Inspection Photos
Location Name: Pierce Unit-Kennedy #3
Location ID: 323392



Photo 5: Unknown contents in container



Photo 6: Container next to pumpjack

Inspection Photos
Location Name: Pierce Unit-Kennedy #3
Location ID: 323392



Photo 7: Containers east of pumpjack



Photo 8: Stained soil