

Inspection Photos

API: 05-073-06321

Operator: NIGHTHAWK PRODUCTION

Inspection Date: 12/18/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06321 | Date: 12/18/2019

Inspection Photos



Photo 1. Facing southeast along the reclaimed access road. Vegetation is establishing along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06321 | Date: 12/18/2019

Inspection Photos



Photo 2. Facing south along the former access road. There is an erosion channel that has formed along the road as it descends the hill slope at Lat/Long:38.94446,-103.57678.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06321 | Date: 12/18/2019

Inspection Photos



Photo 3. The erosion channel deepens as it descends the hill. Arrow points to 3.5 ft. shovel for scale.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06321 | Date: 12/18/2019

Inspection Photos



Photo 4. Facing northeast toward the location. A perimeter fence remains around the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06321 | Date: 12/18/2019

Inspection Photos



Photo 5. Center of the location facing north. Vegetation is well established at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06321 | Date: 12/18/2019

Inspection Photos



Photo 6. Center of the location facing east. Vegetation is well established at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06321 | Date: 12/18/2019

Inspection Photos



Photo 7. Center of the location facing west. Vegetation is well established at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06321 | Date: 12/18/2019

Inspection Photos



Photo 8. Center of the location facing south. Vegetation is well established at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06321 | Date: 12/18/2019

Inspection Photos



Photo 9. Facing west toward the surrounding reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06321 | Date: 12/18/2019