

Inspection Photos Location #447695



location



Hole in s/w corner of location behind tank battery.



Inspection Photos Location #447695



Truck on location pulling production water and no sign of a strong Oder.



Truck on location pulling production water and no sign of a strong Oder.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos Location #447695



Some well heads have wildlife escape boards.



Well heads missing wildlife escape boards.

Inspection Photos Location #447695



Well heads missing wildlife escape boards.



Well heads missing wildlife escape boards.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources