

Ant Hill Unit 36-11, 36-11 BD

API: 05-103-10392, 10393

Inspection: 679706684



Photo 1. Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Ant Hill Unit 36-11, 36-11 BD
API: 05-103-10392, 10393
Inspection: 679706684



40.10522, -108.23205, 5771.9ft, 10°
12/26/2019 10:12:28 AM

Photo 2. Well heads & pig station.

Ant Hill Unit 36-11, 36-11 BD
API: 05-103-10392, 10393
Inspection: 679706684



Photo 3. Meter buildings & separators.



Ant Hill Unit 36-11, 36-11 BD

API: 05-103-10392, 10393

Inspection: 679706684

No bird protection



40.10534, -108.23187, 5771.6ft, 181°

12/26/2019 10:14:25 AM

Photo 4. Tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Ant Hill Unit 36-11, 36-11 BD
API: 05-103-10392, 10393
Inspection: 679706684

Bolt holes




Photo 5. Secondary containment.



Photo 6. Cride tank stack.