

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/26/2019

Submitted Date:

12/27/2019

Document Number:

694400268**FIELD INSPECTION FORM**Loc ID 465709 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Justin Nelson		Justin_Nelson@oxy.com	
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
465709	LOCATION	AC			-	JODSTER SOUTH 24-25HZ PAD	AC

General Comment:

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 465709 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Well Drilling

Rig: Rig Name: _____ Pusher/Rig Manager: _____
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: _____

Comment: COGCC Inspection Report Summary
 On Thursday, December 26th, I supervisor Adam Kraich performed an inspection of the Jodster South 24-25HZ pad, operated by Occidental Petroleum Corporation, in Larimer County, Colorado.
 This inspection is a follow up to inspection document #694400263, that identified potential non compliance of rule 802.b for low frequency noise.
 In this inspection, measurements were taken as guided by rule 802.b.
 A sound survey was performed 25' from the complainants home (40.377551, -104.950916).
AUDIT RESULTS:
 Name S020_BGR100002_27122019_091746
 Start Time 12/26/2019 4:38:09 PM
 Stop Time 12/26/2019 4:58:41 PM
 Device Name BGR100002
 Model Type SoundPro DL
 Device Firmware Rev R.13H
 Comments: Measurement taken from 40.377551, -104.950916. Weather Data: Overcast, 40°, light breeze out of the north.
 Leq 1: 51.9 dB
 Leq 2: 67 dB

 67 DB is non compliance under rule 802.d. A corrective action is assigned to the location, with a timeframe of 72 hours. A follow up inspection will be completed on 12/30/2019.
 I spoke with OXY rig and compliance management on site on 12/26 who have begun mitigation efforts in regard to the low frequency issues.

Corrective Action: **Comply with Rule 802. For low frequency issues, obtain a low frequency impact analysis and identify control measures.**

Date: 12/30/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694400269	Sound Audit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5022656
694400270	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5022657