

# Final Reclamation Inspection

December 19, 2019

Operator: FOUNDATION ENERGY MANAGEMENT LLC- #10112

Location ID: 330622

Inspection Document #: 697500947

Weld County, CO

SWSE Section 31 T8N R60W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: HILL #31-15-8  
Location ID: 330622



**Photo 1.** Photo taken from the western tank battery location, facing East. Photo illustrates Operator has failed to remove all equipment from the location- see Photo 2. COGCC staff could not make a complete vegetation assessment due to snow cover but there appeared to be bare patches throughout portions of the tank battery.

Inspection Photos  
Location Name: HILL #31-15-8  
Location ID: 330622



**Photo 2.** Photo taken from the eastern tank battery location, facing North. Photo illustrates equipment that remains at the tank battery location.