

Interim Reclamation and Stormwater Inspection

December 26, 2019

Operator: VERDAD RESOURCES LLC - #10651

Location ID: 438074

Inspection Document #: 697500969

Weld County, CO

NENE Section 14 T1N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: AMEN /PAD
Location ID: 438074



Photo 1. Photo taken from the location, facing South. Photo illustrates only one well has been drilled. Operator has performed Interim Reclamation activities to reduce all areas only needed for production operations.

Note: Vehicle rutting is evident throughout the location and is not in compliance with Rule 1002.f.

Inspection Photos
Location Name: AMEN /PAD
Location ID: 438074



Photo 2. Photo taken from the western location, facing Southeast. See comments under Photo 1 regarding vehicle rutting.

Inspection Photos
Location Name: AMEN /PAD
Location ID: 438074



Photo 3. Photo taken from the location, facing East. See comments under Photo 1 regarding vehicle rutting.