

## Inspection Photos Location #334679



Location



Location



## Inspection Photos Location #334679



Well is venting from Braden head  
Signage is not correct



Well is venting from Braden head  
Signage is not correct



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos Location #334679



**Another well is venting from Braden head**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources