

**Inspection Photos**  
**Operator: Southland Royalty**  
**Location/API #: 007-06185**  
**Date: 12-30-2019**



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing with intermediate wheatgrass.



Photo 3. View of the southern project area from the southern edge facing eastward.



Photo 4. View of reference area, comprised of open grass field, covered in snow at this time.