

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

12/31/2019

Submitted Date:

01/01/2020

Document Number:

679706761

**FIELD INSPECTION FORM**

Loc ID 335884	Inspector Name: Moran, Rick	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: 100264 Name of Operator: XTO ENERGY INC Address: 110 W 7TH STREET City: FORTH WORTH State: TX Zip: 76102				<b>Findings:</b> 16 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
Reid, Van		van_reid@xtoenergy.com	
Dooling, Jessica	970-769-6048	Jessica_Dooling@xtoenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285712	WELL	PR	06/08/2012	GW	103-10818	PICEANCE CREEK UNIT 296-7A5	PR
285713	WELL	PR	09/10/2019	GW	103-10819	PICEANCE CREEK UNIT 296-7A4	PR
285714	WELL	PR	06/01/2019	GW	103-10820	PICEANCE CREEK UNIT 296-7A3	PR
285715	WELL	SI	10/01/2019	GW	103-10821	PICEANCE CREEK UNIT 296-7A2	SI
285716	WELL	SI	10/01/2019	GW	103-10822	PICEANCE CREEK UNIT 296-7A1	SI
285717	WELL	PR	09/21/2014	GW	103-10823	PICEANCE CREEK UNIT 296-7A9	PR
285718	WELL	PR	06/01/2019	GW	103-10824	PICEANCE CREEK UNIT 296-7A8	PR
285719	WELL	PR	01/17/2009	GW	103-10825	PICEANCE CREEK UNIT 296-7A7	PR
285720	WELL	SI	10/01/2019	GW	103-10826	PICEANCE CREEK UNIT 296-7A6	SI

**General Comment:**

COGCC Inspection Report Summary.

On 12-31-2019 at approximately 12:05, inspector Rick Moran, conducted a routine inspection at XTO Energy well pad Piceance Creek Unit 296-7A in Rio Blanco county.

The following compliance issues were observed:

- 1) Square container without a label. Photo 6. Complete by 3-1-2020.

A follow up inspection will occur to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679706761.

### Location

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	Last recorded production September 2019.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	03/01/2020
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	OTHER		
Comment:	Chemical.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Other	# 5		
Comment:	Well manifold, 3 tailers with equipment, 1 skid trailer with equipment.		
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:	In building.		
Corrective Action:		Date:	
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 6		

Comment:	Container of PS-532, 1 container of diesel, 3 containers of SCI-8760, and 1 container of unknown.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	400 BBLs	STEEL AST		39.892490,-108.203630	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient		Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 285712	Type: WELL	API Number: 103-10818	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR				
Corrective Action:			Date:	
Facility ID: 285713	Type: WELL	API Number: 103-10819	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR				
Corrective Action:			Date:	
Facility ID: 285714	Type: WELL	API Number: 103-10820	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR				
Corrective Action:			Date:	
Facility ID: 285715	Type: WELL	API Number: 103-10821	Status: SI	Insp. Status: SI
<b>Idle Well</b>				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned    Reminder: _____				
Comment: Last recorded production September 2019.				
Corrective Action:			Date:	
Facility ID: 285716	Type: WELL	API Number: 103-10822	Status: SI	Insp. Status: SI
<b>Idle Well</b>				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned    Reminder: _____				
Comment: Last recorded production September 2019.				
Corrective Action:			Date:	
Facility ID: 285717	Type: WELL	API Number: 103-10823	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR				
Corrective Action:			Date:	
Facility ID: 285718	Type: WELL	API Number: 103-10824	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR				
Corrective Action:			Date:	
Facility ID: 285719	Type: WELL	API Number: 103-10825	Status: PR	Insp. Status: PR

**Producing Well**Comment: [PR](#)

Corrective Action:

Date:

Facility ID: 285720 Type: WELL API Number: 103-10826 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: [Last recorded production September 2019.](#)

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	284684	200090057	
	284684	200090057	

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679706762	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5026072">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5026072</a>