

Inspection Photos

Location Name: BODDINGTON 43-17 CA DATE 1-3-2020

API#: 05-071-06702

INSP. #: 695101947



Colorado Oil & Gas Conservation Commission
37.25662, -104.68847, 2200.0m, 255°
2020/01/02 12:24:38

PHOTO 1: WELLHEAD



Colorado Oil & Gas Conservation Commission
37.25672, -104.68861, 2232.0m, 195°
2020/01/02 12:25:08

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: BODDINGTON 43-17

API#: 05-071-06702

INSP. #: 695101947



PHOTO 3: 2" LINE TO PIT IS DISCONNECTED AND WELL IS LEAKING PRODUCED WATER ONTO LOCATION, PRODUCED WATER IS RUNNING DOWN DITCH ON LOCATION INTO PRODUCE WATER EARTH PIT. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. CA DATE 1-3-2020