

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/03/2020

Submitted Date:

01/03/2020

Document Number:

679602094**FIELD INSPECTION FORM**Loc ID 336684 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242960	WELL	PR	06/01/2019	GW	123-10751	LUNDVALL 3	TA
281206	WELL	PR	08/01/2019	GW	123-23352	STEVE J 30-4J	TA
281207	WELL	PR	12/28/2005	GW	123-23353	STEVE J 30-6	TA

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate (x3)		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment at each wellhead. See attached photos.		
Corrective Action:	Comply with Rule 603.f.	Date:	01/10/2020

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	60 BBLs	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with crude oil tank.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.377400,-104.831200
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 242960 Type: WELL API Number: 123-10751 Status: PR Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: SITE CONDITIONComment: PA; FORM 42 DOC#: 402195516 in well file, awaiting Form 6(s) to be filed for completion of plug and abandonment.Corrective Action:  Date: Facility ID: 281206 Type: WELL API Number: 123-23352 Status: PR Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: SITE CONDITIONComment: PA; Form 42 DOC#: 402190936 in well file; awaiting Form 6(s) to be filed for completion of plug and abandonment.Corrective Action:  Date: Facility ID: 281207 Type: WELL API Number: 123-23353 Status: PR Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: SITE CONDITIONComment: PA; Form 42 DOC#: 402195513 in well file, awaiting Form 6(s) to be filed for completion of plug and abandonment.Corrective Action:  Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<b>COGCC Inspection Report Summary</b> <b>**Weather Conditions: sunny, snow on ground</b>  On Friday, January 3, 2020 at approximately 11:20, I, Inspector Brittani Santistevan, conducted an on-site inspection at STEVE J 30-4J, STEVE J 30-6, LUNDVALL 3 (Noble Energy), at location #: 336684 in WELD COUNTY Colorado. While there, I observed temporarily abandoned wellheads and shut in tank battery. During this inspection the following possible compliance issues were observed: 1. Unused equipment at each wellhead. REMOVE TO COMPLY WITH RULE 603.F. (Corrective Action Date: January 10, 2020) See attached photos #1-6.  A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.	santistb	01/03/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679602095	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5028195">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5028195</a>