

Well Name: Elsa 34-6-19 # 1 API # 05-067-09922
Elsa 34-6-19 # 2 API # 05-067-09945
Inspection Number: 685305469
Action Completed: 10/18/2018
Corrective Action Taken: Removed oily circular stains.
Removed rig anchors
Installed oil containment pans under lube oil tanks
Filled in and packed hole in berm left by animal burrow

