

Inspection Photos

Loc#420972

Operator: Terra

Inspection Number: 692401763

Inspection Date: 12/23/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from Entry and view down Access road.

December 23, 2019



Photo#2:
Weedy / unused area of Pad.




Photo#3:
Close up of Weedy area of pad.

December 23, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra CDOW Loc#420970



Photo#4:
Weedy berm /slope.



Photo#5:
Weedy berm /slope.



December 23, 2019



Photo#6:
Area of Curly Dock Viewed from below site, looking
up from access road.

Photo#7:
Curly Dock in upper Reclamation area.

December 23, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra CDOW Loc#420970