

# *Inspection Photos*

*Loc#435118*

*Operator: Terra*

*Inspection Number: 692401764*

*Inspection Date: 12/23/19*




**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to South & North; Areas no Longer needed for use.

December 23, 2019





Photo#2:  
Weedy Interim area.



Photo#3:  
Weedy Interim area.




December 23, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra State KP Loc#435118



Photo#4:  
Aerial view of Location.

December 23, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra State KP Loc#435118