



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Luis Guerrero (l.guerrero@kosinm.com)
Submission Date:	Dec 13, 2019 8:39:15 AM MST
Server Receive Date:	Dec 13, 2019 8:39:21 AM MST
Reference Number:	20191213-18126247831
Location:	15731 US-550, Bloomfield, NM 87413, USA Dec 13, 2019 8:33:44 AM MST [ <a href="#">View Map</a> ]

## Information

Name	l.guerrero@kosinm.com
Date	Sep 25, 2019
Well Name	MARTIN, JOE GAS UNIT 2
API Number	50670865500
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Erosion Repairs Install Rock Run Down

Photo of first corrective action completed



Completed work description Corrective Action 1

Installed rock armored silt bowl

Photo of second corrective action completed



Completed work description of corrective action 2

Built berm to divert storm water into silt bowl

Completed work description of corrective action 3

Completed work description of corrective action 4

Summary of all work completed

.

.

Repaired erosion channel, installed rock armored silt bowl, repaired storm water diversion berm