



Form Information

| | |
|----------------------|--|
| Form Name: | Compliance Follow Up Form |
| Submitter Name: | Cole Nichols (colen@horizonenvservices.com) |
| Submission Date: | Dec 13, 2019 1:01:08 PM MST |
| Server Receive Date: | Dec 13, 2019 1:03:28 PM MST |
| Reference Number: | 20191213-18126275148 |
| Location: | 557 Airpark Dr, Durango, CO 81303, USA Dec 13, 2019 1:00:09 PM MST [View Map] |

Information

| | |
|-----------------------|------------------------------|
| Name | colen@horizonenvservices.com |
| Date | Dec 11, 2019 |
| Location Name (Other) | State MZ 2 |
| Location API (Other) | 0506710003 |
| Select State | Colorado |
| Work type | COGCC Inspection AR |
| Action Complete | Clean Up Weed Debris |

Photo of first corrective action completed



Completed work description Corrective Action 1 sign

Photo of second corrective action completed



Completed work description of corrective action 2 before mowing

Photo of third corrective action completed



Completed work description of corrective action 3
Photo of fourth corrective action completed

after mowing



Completed work description
Completed work description of corrective action 4

before mowing
mowed and removed weed debris from around the equipment

Additional photos



Additional photos



Additional photos



Completed work description

Summary of all work completed

mowed and removed weed debris from around the equipment

initial treatment was on 7/11/19, second treatment was on 11/4/19