




Form Information

Form Name: **Compliance Follow Up Form**
Submitter Name: Cole Nichols (colen@horizonenvservices.com)
Submission Date: Dec 13, 2019 1:12:36 PM MST
Server Receive Date: Dec 13, 2019 1:14:55 PM MST
Reference Number: 20191213-18126275670
Location: 557 Airpark Dr, Durango, CO 81303, USA
Dec 13, 2019 1:14:26 PM MST [[View Map](#)]

Information

Name colen@horizonenvservices.com
Date Dec 11, 2019
Well Name FRAHM FEDERAL GAS UNIT 2
API Number 50670886200
Select State Colorado
Work type COGCC Inspection AR
Action Complete Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

sign

Photo of second corrective action completed



Completed work description of corrective action 2

removed weed debris from around equipment

Photo of third corrective action completed



Completed work description of corrective action 3
 Photo of fourth corrective action completed

removed weed debris from around equipment



Completed work description
 Completed work description of corrective action 4
 Additional photos

removed weed debris from around equipment
 removed weed debris from around equipment



Completed work description
 Summary of all work completed

mowed and removed weed debris from around
 equipment- this is a no spray site
 initial removal on 4/9/19, second removal on 7/10/19