



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Dec 13, 2019 1:21:36 PM MST
Server Receive Date:	Dec 13, 2019 1:23:58 PM MST
Reference Number:	20191213-18126276844
Location:	557 Airpark Dr, Durango, CO 81303, USA Dec 13, 2019 1:21:25 PM MST [View Map]

Information

Name	colen@horizonenvservices.com
Date	Dec 12, 2019
Well Name	FRAHM GAS UNIT 15-01 1
API Number	50670671700
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

sign

Photo of second corrective action completed



Completed work description of corrective action 2

removed weed debris from around equipment

Photo of third corrective action completed



Completed work description of corrective action 3
 Photo of fourth corrective action completed

removed weed debris from around equipment



Completed work description
 Completed work description of corrective action 4
 Additional photos

removed weed debris from around equipment
 removed weed debris from around equipment



Additional photos



Completed work description
Summary of all work completed

removed weed debris from around equipment
initial removal on 4/9/19, second removal on 7/10/19