



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Luis Guerrero (l.guerrero@kosinm.com)
Submission Date:	Dec 30, 2019 7:53:30 AM MST
Server Receive Date:	Dec 30, 2019 7:53:40 AM MST
Reference Number:	20191230-18128113861
Location:	15731 US-550, Bloomfield, NM 87413, USA Dec 30, 2019 7:52:57 AM MST [View Map]

Information

Name	l.guerrero@kosinm.com
Date	Dec 26, 2019
Well Name	SHARP, MF GAS UNIT A 1
API Number	50670726600
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Clean up Operator Debris Repaired Berm Replaced/Repaired Tank Signs

Photo of first corrective action completed



Completed work description Corrective Action 1

Cleaned up stained soils.

Photo of second corrective action completed



Completed work description of corrective action 2
Photo of third corrective action completed



Removed weeds from inside fence area.

Completed work description of corrective action 3
Photo of fourth corrective action completed



Removed unused equipment.

Completed work description of corrective action 4
Additional photos



Repaired berms around tanks.

Additional photos



Additional photos



Additional photos



Summary of all work completed

Cleaned up stained soils around the wellhead.
Removed weeds and unused equipment. Installed new tank signs and removed all trash and debris.